 AK Produktionstechnik	<b>QA Agreement for Suppliers</b>	<b>QSV 7.4-3</b>
		Page 1 of 2
		Document shall be used in QM, Cost

By:
Company:

## Distributor and Scope of Application:

This Quality Assurance Agreement (QSV) is to be adhered to by all suppliers involved in the handling, finishing or delivery of our product as stipulated in the order.

## Reference Document

EN 9100 Quality Management System Aerospace

## Points to be observed:

### General


1. Please comply with all requirements concerning your order. The accompanying documents include all the necessary steps in the work process with drawings if applicable.
2. Please check that the specified requirements are complete and accurate before delivery.
3. Please only use transport containers which protect the goods well or have been provided by us when returning processed materials / products.
4. On no account should deliveries which have been sent separately or in several single shipments be combined. In this case it is absolutely essential to keep these production batches separate.

## Arrangement of Confidentiality

5. All information concerning order processing is to be treated with the strictest confidence.

## Specific Points for Aerospace

6. Your deliveries will be periodically checked. If the deliveries do not meet the specified requirements we reserve the right to return all the goods and to charge a handling fee.
7. We must be informed of faulty products before delivery or, as the case may be, delivery must be approved. If faults are detected after delivery we must be informed immediately.
8. Initial sample – new parts are to be delivered with an initial sample test report which includes proof of compliance with all features.
9. Qualification of personnel – the personnel must have the necessary qualifications. The results of exams requiring verification ( e.g non-destructive examinations) are to be released on request.

	<b>QA Agreement for Suppliers</b>	<b>QSV 7.4-3</b>
		Page 2 of 2
		Document shall be used in QM, Cost

10. The supplier maintains a quality management system of at least ISO 9001 or of a superior grade.

11. The designation or exact identification as well as the respective specification, drawings, process requirements, instructions and other relevant technical data are to be stated in the order.

12. If necessary, requests for development, tests, inspection and examination are to be given in the order.

13. If necessary, audits are to be carried out at the supplier.

### Amendments

14. The supplier grants right of access to the ordering party and his customers as well as to the aeronautical authorities in all facilities involved in the order as well as in all relevant records.

### Subcontracting

15. Subcontracting is only permitted after prior permission from us. The same quality management requirements apply as defined in this quality assurance agreement. In this case, we reserve the right to audit the subcontractor. Only approved sources should be used.

### Inspection

16. For each delivery, we expect a certificate of compliance to EN 10204-2.1. Higher Certificates are provided in our order.

17. Customers or customer representatives are entitled to conduct a verification at the location of the supplier in regard to the agreement concerning the specified requirements of the subcontracted items.

AK-Produktionstechnik	Daisendorf,	
	Place, date	name, official stamp, signature
Supplier		
	Place, date	name, official stamp, signature